

	Type	Hits	Search Text
1	BRS	1201	347/20
2	BRS	674	347/22
3	BRS	970	347/29
4	BRS	743	valve\$1 and cap\$ and filter\$1 and (printhead\$1 or (print\$3 adj head\$1))
5	BRS	273	valve\$1 and cap\$1 and filter\$1 and (printhead\$1 or (print\$3 adj head\$1))
6	BRS	39	(valve\$1 and cap\$1 and filter\$1 and (printhead\$1 or (print\$3 adj head\$1))) and (347/20 or 347/22 or 347/29)
7	BRS	17	(((print\$3 adj head\$1) or printhead\$1) same (dust\$3 adj (remov\$3 or clean\$3)))

	DBs	Time Stamp	Comments	Error Definition
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:38		
2	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:38		
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:39		
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:42		Truncation overflow.
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:42		
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/21 12:43		
7	USPAT; US-PGPUB; EPO; JPO; DERWENT	2002/11/22 13:48		

Errors	
1	0
2	0
3	0
4	1
5	0
6	0
7	0